



BT08WWC

SAJAC051097R23887

JAGUAR- XF LUXURY D V6 A-

2008 • RED • DIESEL

Report ID: BT08WWC-LPX1OWPR

Report Date: 15 January 2026

Critical Checks

Outstanding Finance	Has finance agreement
Condition/Write Off	No Condition/Write Off recorded
Stolen	Not recorded as stolen
High Risk	Not at risk
Certificate of Destruction	False

Important Checks

Previous Keepers	7
Plate Change	6
Colour Change	No
Scrapped	No
Previous N.Ireland	No
VIC Inspected	No
VIN	SAJAC051097R23887
Engine Number	03271967G
Imported	No
V5C count	8

Outstanding Finance Check

Finance Record Count	1
Agreement Date	05-12-2016
Agreement Type	CONDITIONAL SALE
Agreement Term	108
Vehicle Description	JAGUAR XF DIESEL SALOON P
Agreement Number	05674585
Finance Company	CLOSE MOTOR FINANCE LTD
Contact Number	01782 572220

Outstanding Finance Alert: This vehicle has outstanding finance. Before making a purchase, please contact the finance company using the information provided in the report, including the finance company name, agreement number, and contact details, to ensure the finance is cleared.

*Finance data provided by Experian

Condition/Write Off Details

Write Off Count

0

Condition/Write Off Alert: This vehicle has been marked as written off, potentially due to accident damage or theft. We recommend thoroughly reviewing the details and contacting the seller for more information before proceeding with the purchase. It's essential to understand the extent of the damage and repairs made.

Stolen

Stolen Record Count

0

Stolen Vehicle Alert: This vehicle has been flagged as stolen in the UK Police database. Do not proceed with the purchase. We advise you to immediately contact the Police to report the incident and avoid any potential legal issues.

High Risk

High Risk Record Count

0

High Risk Alert: This vehicle is flagged as high risk, often due to a financial dispute over ownership. A third party may be tracking the vehicle to prevent its sale. We strongly recommend investigating further and contacting the relevant parties before proceeding with the purchase.

Valuation

On the Road (OTR)	£33,115
Dealer Forecourt	£2,948
Trade Retail	£2,634
Private Clean	£1,822
Private Average	£1,975
Part Exchange	£2,014
Auction	£1,604
Trade Average	£1,297
Trade Poor	£1,106

Valuations are provided on estimated mileage of 94,284 and valued on 15 January 2026
(*provided where available)

Previous Keeper's History

Previous Keeper	Date of Transaction
7	26-04-2023
6	01-07-2022
5	07-05-2022
4	06-05-2021
3	03-12-2016
2	02-12-2013
1	19-03-2012

Plate Change

Date of Transaction	Previous VRM	Current VRM
14-11-2025	C90NKO	BT08WWC
02-05-2023	BT08WWC	C90NKO
16-03-2021	P200JCH	BT08WWC
21-12-2016	BT08WWC	P200JCH
17-11-2016	K2NTA	BT08WWC
19-12-2013	BT08WWC	K2NTA

Tax & MOT

MOT Status	Expiring (108 Days left)
MOT Due	03-05-2026
MOT Advisory	Has Advisory
Tax	Expires: 01-05-2026
MOT Record Count	23

Mileage Checks

Mileage	94,284 (Low) miles
Mileage issues	No Issues Detected
Mileage Last Year	3,333 miles
Avg Mileage	5,357 miles
Mileage Status	Low

Vehicle Specification

Make	JAGUAR
Model	XF LUXURY D V6 A
Model Variant	XF Luxury D V6 Auto
Colour	RED
Fuel Type	Diesel
Engine Size	2720 cc
Wheel Plan	2 AXLE RIGID BODY
Exported	No
Type Approval Category	M1
Transmission	Automatic
No. of Doors	4
No. of Seats	5
No. of Gears	6
Body Type	Saloon

Vehicle Registration

Vehicle age	17y 6m
First Registration	23-06-2008
Year of Manufacture	2008
Last V5C Issue Date	03-05-2023
Time Since Last V5C	2y 8m
Euro Status	4
ULEZ Compliance	Check
Safety Recalls	Check

Running Cost

Fuel Cost	£2027.29
MOT	£54.98
TAX - 6 Months (Standard rates)	£217.25
TAX - 12 Months (Standard rates)	£395
TAX - 6 Months (Premium rates)	-
TAX - 12 Months (Premium rates)	-


Performance

Top Speed	143 Mph (230 Kph)
Power RPM	4000
Power BHP	203.8
Power Kw	152
Torque - Rpm	1900
Torque - FtLb	321
Torque - Nm	435

Economic and environmental details


199 g/km (K)

0




A

1 - 75




BC

76 - 100




DE

101 - 130




FG

131 - 170




HI

171 - 225



JK

226 - 256+



LM

Fuel Consumption

mpg

Extra Urban

48.7

Combined

37.7

UrbanCold

27.2

Co2 Emission

199 g/km

Ved Co2 Band

"K"

Mileage History

Date	Mileage	Yearly Total
23-04-2025	94,284	3,333
12-04-2024	90,951	6,140
13-04-2023	84,811	5,301
04-05-2022	79,510	555
01-03-2022	78,955	3,924
25-03-2021	75,031	4,758
16-06-2020	70,273	-

MOT History of the Vehicle

Date	Test Result	Mileage	Advisory Notices	Failure Notices
23-04-2025	Passed	94,284	Central Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)), Central Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)),	No Failure Notices

Date	Test Result	Mileage	Advisory Notices	Failure Notices
22-04-2025	Failed	94,236	Central Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)), Central Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)),	Nearside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)), Nearside Rear Inner Steering linkage ball joint ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)), Nearside Rear Outer Steering linkage ball joint ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)), Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i)), Offside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)), Offside Rear Inner Steering linkage ball joint ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)), Offside Rear Outer Steering linkage ball joint ball joint dust

Date	Test Result	Mileage	Advisory Notices	Failure Notices
12-04-2024	Passed	90,951	Front Brake disc worn, but not excessively (1.1.14 (a) (i)), Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Rear Brake disc worn, but not excessively (1.1.14 (a) (i)), Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)),	No Failure Notices

Date	Test Result	Mileage	Advisory Notices	Failure Notices
11-04-2024	Failed	90,935	Front Brake disc worn, but not excessively (1.1.14 (a) (i)), Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)), Rear Brake disc worn, but not excessively (1.1.14 (a) (i)), Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)),	Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d)),
13-04-2023	Passed	84,811	No Advisory Notices	No Failure Notices

Date	Test Result	Mileage	Advisory Notices	Failure Notices
13-04-2023	Failed	84,811	No Advisory Notices	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)), Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)),
04-05-2022	Passed	79,510	engine cover fitted, under-tray fitted,	No Failure Notices
04-05-2022	Failed	79,510	engine cover fitted, under-tray fitted,	Nearside Front Position lamp not working (4.2.1 (a) (ii)), Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)), Offside Registration plate lamp likely to become detached (4.7.1 (c) (ii)),
01-03-2022	Passed	78,955	Nearside Rear Service brake binding but not excessively (1.2.1 (f)),	No Failure Notices

Date	Test Result	Mileage	Advisory Notices	Failure Notices
28-02-2022	Failed	78,947	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)), Nearside Rear Service brake binding but not excessively (1.2.1 (f)),	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)), Offside Front Position lamp not working (4.2.1 (a) (ii)), Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)), Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a)),
25-03-2021	Passed	75,031	No Advisory Notices	No Failure Notices
16-06-2020	Passed	70,273	Brake hose has slight corrosion to ferrule both fronts (1.1.12 (f) (i)), Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)), Front Brake pad(s) wearing thin (1.1.13 (a) (ii)),	No Failure Notices

Date	Test Result	Mileage	Advisory Notices	Failure Notices
15-06-2020	Failed	70,273	Brake hose has slight corrosion to ferrule both fronts (1.1.12 (f) (i)), Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)), Front Brake pad(s) wearing thin (1.1.13 (a) (ii)),	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)), Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)), Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii)),
24-01-2019	Passed	58,189	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i)), Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)),	No Failure Notices

Date	Test Result	Mileage	Advisory Notices	Failure Notices
23-01-2019	Failed	58,166	Front Items removed from driver's view prior to test (), Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)), Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i)), Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)), Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)), Offside Front has string repair, Windscreen damaged but not adversely affecting driver's view miner stone chips both zones (3.2 (a) (i)), engine/underside body covers/trays fitted*, front center grill Damaged, but not likely to cause injury when grazed or contacted, smoke test too clean reading 0,	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)),

Date	Test Result	Mileage	Advisory Notices	Failure Notices
04-01-2018	Passed	45,190	No Advisory Notices	No Failure Notices
30-12-2017	Failed	45,095	No Advisory Notices	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g), Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g),

Date	Test Result	Mileage	Advisory Notices	Failure Notices
11-05-2016	Passed	31,654	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i), Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i), Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i), Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i), all tyres tread getting low, engine covers fitted obscuring some components in the engine bay, under-trays fitted obscuring some underside components,	No Failure Notices
15-04-2015	Passed	24,580	Under-trays fitted obscuring some underside components,	No Failure Notices

Date	Test Result	Mileage	Advisory Notices	Failure Notices
25-04-2014	Passed	18,505	No Advisory Notices	No Failure Notices
22-03-2013	Passed	13,599	No Advisory Notices	No Failure Notices
23-03-2012	Passed	5,692	No Advisory Notices	No Failure Notices
18-06-2011	Passed	5,121	No Advisory Notices	No Failure Notices